

उत्तराखण्डप्रदूषणनियंत्रण बोर्ड गौरादेवीपर्यावरणभवन 46—बी, सिडकुल,आई.टी. पार्क, सहस्त्रधारारोड़, देहरादून(उत्तराखण्ड)

CENTRAL LABORATORY

Analysis Report of Sewage Treatment Plants (STPs) for the Month of July 2023

| o v: | I | Sampling Point | | | | | | | | |
|-------|---|---|------------|-----|---------------|------|-----|--------------------|--|--|
| S.No. | Name of the Sewage Treatment Plant (With Capacity) | | nlet of ST | P | Outlet of STP | | | | | |
| | | pН | BOD | TSS | pН | BOD | TSS | Fecal Coliform | | |
| 1 | 0.010 MLD STP Near Temple at Badrinath. (Operated by: Uttarakhand Jal Sansthan) | As the area around the STP comes under Master Plan so the demostructure work around the STP was in progress and the STP wasnon-op due to the same reason. (Date of inspection: 22-07-2023). | | | | | | | | |
| 2 | 0.26 MLD STP Near Bamni Gaon, Badrinath. (Operated by: Uttarakhand Jal Sansthan) | 6.85 | 170 | 176 | 7.20 | 10 | 14 | 1600 | | |
| 3 | 1.0 MLD STP Near Suspension Bridge, Badrinath. (Operated by: Uttarakhand Jal Sansthan) | 7.10 | 180 | 185 | 8.13 | 8.8 | 11 | 540 | | |
| 4 | 2.70 MLD STP at Marwari, Joshimath. (Operated by: Uttarakhand Peyjal Nigam) | 7.20 | 110 | 113 | 7.80 | 8.4 | 10 | 130 | | |
| 5 | 1.080 MLD STP at Pokhri, Joshimath. (Operated by: Uttarakhand Jal Sansthan) | STP found Non-Operational at the time of inspection as no effluent was reaching to the plant. (Date of Inspection: 22-07-2023). | | | | | | | | |
| 6 | 0.075 MLD STP Near Anoop Negi School, Rudraprayag. (Operated by: Uttarakhand Jal Sansthan) | STP is not in operation due to damage of STP. | | | | | | | | |
| 7 | 0.100 MLD STP, Near Rudra Complex, Rudraprayag. (Operated by: Uttarakhand Peyjal Nigam) | 7.10 | 130 | 128 | 7.20 | 8.8 | 10 | 1600 | | |
| 8 | 0.075 MLD STP, Near Bus Stand, Rudraprayag. (Operated by: Uttarakhand Peyjal Nigam) | 7.01 | 125 | 122 | 7.52 | 9.2 | 11 | 22×10 ² | | |
| 9 | 0.100MLD STP, Near SBI & Maszid, Rudraprayag. (Operated by: Uttarakhand Peyjal Nigam) | 6.90 | 145 | 142 | 7.11 | 9.2 | 10 | 1600 | | |
| 10 | 0.125 MLD STP, Near Steel Bridge & Syndicate Bank, Rudraprayag . (Operated by: Uttarakhand Jal Sansthan) | 7.05 | 130 | 126 | 7.70 | 8.8 | 09 | 280 | | |
| 11 | 0.050 MLD STP at Beleni Road, Near Steel Bridge, Rudraprayag. (Operated by: Uttarakhand Peyjal Nigam) | 6.90 | 160 | 162 | 7.20 | 10.8 | 14 | 350 | | |
| 12 | 3.5 MLD STP at Nursary Road, Srinagar. (Operated by: Uttarakhand Peyjal Nigam) | 6.88 | 210 | 213 | 7.20 | 9.2 | 11 | 430 | | |
| 13 | 1.0 MLD STP, Near ITI, Srinagar. (Operated by: Uttarakhand Jal Sansthan) 0.075 MLD STP Near Junior High | 6.80 | 195 | 193 | 7.40 | 8.8 | 09 | 94 | | |
| 14 | School, Srikot, Srinagar. (Operated by: Uttarakhand Peyjal Nigam) | 6.90 | 120 | 118 | 8.50 | 9.2 | 11 | 240 | | |



उत्तराखण्डप्रदूषणनियंत्रण बोर्ड गौरादेवीपर्यावरणभवन 46—बी, सिडकुल,आई.टी. पार्क, सहस्त्रधारारोड़, देहरादून(उत्तराखण्ड)

CENTRAL LABORATORY

| | | Sampling Point | | | | | | | |
|-------|---|---|-----|-----|------|------|-----|--------------------|--|
| S.No. | Name of the Sewage Treatment Plant (With Capacity) | Inlet of STP Outlet of STP | | | | | | | |
| | | рН | BOD | TSS | рН | BOD | TSS | Fecal Coliform | |
| 15 | 0.050 MLD STP Near Tauliya Nala, Srikot, Srinagar. (Operated by: Uttarakhand Peyjal Nigam) | 7.10 | 125 | 122 | 7.47 | 8.0 | 09 | 170 | |
| 16 | 0.050 MLD STP, Near BRO Bridge, Kirtinagar. (Operated by: Uttarakhand Jal Sansthan) | 6.80 | 160 | 165 | 7.10 | 10 | 14 | 28×10 ² | |
| 17 | 0.010 MLD STP, Near Temple, Kirtinagar. (Operated by: Uttarakhand Jal Sansthan) | 6.60 | 150 | 153 | 8.80 | 9.6 | 11 | 16×10 ³ | |
| 18 | 0.075 MLD STP at Devprayag. (Operated by: Uttarakhand Peyjal Nigam) | 6.43 | 180 | 178 | 7.80 | 9.2 | 10 | 540 | |
| 19 | 0.150 MLD MLD STP at Devprayag. (Operated by: Uttarakhand Peyjal Nigam) | 6.50 | 190 | 186 | 7.50 | 10 | 12 | 280 | |
| 20 | 1.4 MLD STP at Pauri Road, Devprayag. (Operated by: Uttarakhand Jal Sansthan) | 6.80 | 175 | 172 | 7.28 | 9.6 | 10 | 350 | |
| 21 | 5.0 MLD STP at Bhagirathi Puram, Tehri. (Operated by: Uttarakhand Jal Sansthan) | 6.52 | 185 | 187 | 6.89 | 10 | 13 | 430 | |
| 22 | 2.0 MLD STP at Gyansu, Uttarkashi. (Operated by: Uttarakhand Jal Sansthan) | 7.15 | 210 | 212 | 8.30 | 8.8 | 10 | 220 | |
| 23 | 3.5 MLD STP at Tapovan, Rishikesh. (Operated by: Uttarakhand Jal Sansthan) | 6.80 | 190 | 195 | 7.05 | 10.8 | 14 | 1600 | |
| 24 | 3.0 MLD STP at Swargashram, Rishikesh. (Operated by: Uttarakhand Jal Sansthan) | 7.60 | 210 | 212 | 7.70 | 10 | 11 | 540 | |
| 25 | 26 MLD STP at Lakkarghat, Rishikesh. (Operated by: Uttarakhand Peyjal Nigam) | 7.20 | 170 | 168 | 7.50 | 9.6 | 11 | 84 | |
| 26 | 5.0 MLD STP at Chorpani, | 7.60 | 185 | 183 | 7.80 | 10 | 12 | 94 | |
| 26 | Rishikesh. (Operated by: Uttarakhand Peyjal Nigam) | STP was operational but some untreated/Raw effluent was foun through channel and gets directly discharged into Chandrabhaga Finspection: 14-07-2023). | | | | | | | |
| 27 | 7.5 MLD STP at Chandreshwar Nagar, Rishikesh. (Operated by: Uttarakhand Peyjal Nigam) | 7.10 | 165 | 162 | 7.30 | 9.6 | 11 | 79 | |
| 28 | 20 MLD STP at Motharawala-I, Dehradun. (Operated by: Uttarakhand Jal Sansthan) | 7.30 | 160 | 164 | 7.39 | 9.6 | 12 | 130 | |
| 29 | 20 MLD STP at Motharawala-II, Dehradun. (Operated by: Uttarakhand Jal Sansthan) | 7.20 | 155 | 158 | 7.65 | 8.8 | 10 | 170 | |



उत्तराखण्डप्रदूषणनियंत्रण बोर्ड गौरादेवीपर्यावरणभवन 46—बी, सिडकुल,आई.टी. पार्क, सहस्त्रधारारोड़, देहरादून(उत्तराखण्ड)

CENTRAL LABORATORY

| | | Sampling Point | | | | | | | |
|-------|---|---|-----|-----|------|---------------|-----|----------------|--|
| S.No. | Name of the Sewage Treatment Plant (With Capacity) | Inlet of STP | | | | Outlet of STP | | | |
| | | рН | BOD | TSS | рН | BOD | TSS | Fecal Coliform | |
| 30 | 68 MLD STP at Kargi, Dehradun. (Operated by: Uttarakhand Jal Sansthan) | 7.20 | 170 | 168 | 8.05 | 9.6 | 11 | 94 | |
| 31 | 0.42 MLD STP at Vijay Colony, Dehradun. (Operated by: Uttarakhand Jal Sansthan) | 7.13 | 165 | 161 | 7.55 | 9.2 | 09 | 120 | |
| 32 | 0.71 MLD STP Salawala, Dehradun. (Operated by: Uttarakhand Jal Sansthan) | 7.10 | 170 | 167 | 7.40 | 9.2 | 11 | 110 | |
| 33 | 5.0 MLD STP at Indira Nagar, Dehradun. (Operated by: Uttarakhand Jal Sansthan) | 7.19 | 170 | 172 | 7.50 | 8.8 | 10 | 170 | |
| 34 | 1.0 MLD STP at Jakhan, Dehradun. (Operated by: Uttarakhand Jal Sansthan) | 7.02 | 155 | 159 | 7.58 | 9.2 | 12 | 150 | |
| 35 | 27 MLD STP at Jagjeetpur, Haridwar. (Operated by: Uttarakhand Jal Sansthan) | 7.24 | 180 | 205 | 7.53 | 12 | 10 | 110 | |
| 36 | 18 MLD STP at Jagjeetpur, Haridwar. (Operated by: Uttarakhand Jal Sansthan) | 7.30 | 210 | 175 | 7.45 | 8.0 | 09 | 94 | |
| 37 | 68 MLD STP at Jagjeetpur, Haridwar. (Operated by: Uttarakhand Peyjal Nigam) | 7.34 | 150 | 160 | 7.52 | 8.0 | 07 | 79 | |
| 38 | 18 MLD STP at Sarai, Haridwar. (Operated by: Uttarakhand Jal Sansthan) | 7.40 | 180 | 210 | 7.60 | 9.2 | 10 | 84 | |
| 39 | 14 MLD STP at Sarai, Haridwar. (Operated by: Uttarakhand Peyjal Nigam) | 7.56 | 190 | 190 | 7.73 | 8.0 | 09 | 94 | |
| 40 | 33 MLD STP at Saliyar, Roorkee, Haridwar. (Operated by: Uttarakhand Jal Sansthan) | 7.64 | 220 | 240 | 7.82 | 24 | 30 | 920 | |
| 41 | 1.3 MLD STP at Landour (S), Mussoorie. (Operated by: Uttarakhand Jal Sansthan) | 7.05 | 165 | 163 | 8.80 | 9.2 | 11 | 120 | |
| 42 | 3.12 MLD STP at Bhatta fall, Mussoorie. (Operated by: Uttarakhand Jal Sansthan) | 7.08 | 155 | 151 | 7.90 | 8.8 | 09 | 79 | |
| 43 | 0.8 MLD STP at Landour (N), Mussoorie. (Operated by: Uttarakhand Jal Sansthan) | 7.30 | 175 | 172 | 8.60 | 9.6 | 11 | 150 | |
| 44 | 1.2 MLD STP at Happy Valley, Mussoorie. (Operated by: Uttarakhand Jal Sansthan) | STP was found closed and non operational at the time of visit and also no any representative was present there. (Date of inspection: 10-07-2023). | | | | | | | |
| 45 | 0.9 MLD STP at Kurli Bazaar, Mussoorie. (Operated by: Uttarakhand Jal Sansthan) | 6.60 | 190 | 186 | 8.20 | 9.6 | 10 | 240 | |
| 46 | 2.0 MLD STP Bakh, Almora, Distt- Almora. (Operated by: Uttarakhand Jal Sansthan) | 6.67 | 210 | 263 | 8.10 | 14 | 18 | 130 | |
| 47 | 0.45 MLD STP at Hari Nagar, Distt- Nainital.(Operated by: Uttarakhand Jal Sansthan) | 6.84 | 190 | 238 | 7.53 | 22 | 27 | 150 | |



उत्तराखण्डप्रदूषणनियंत्रण बोर्ड गौरादेवीपर्यावरणभवन 46—बी, सिडकुल,आई.टी. पार्क, सहस्त्रधारारोड़, देहरादून(उत्तराखण्ड)

CENTRAL LABORATORY

| | | Sampling Point | | | | | | | |
|-------|---|----------------|-----------|-------|---------------|-----|------|----------------|--|
| S.No. | Name of the Sewage Treatment Plant (With Capacity) | Inlet of STP | | | Outlet of STP | | | | |
| | | рН | BOD | TSS | рН | BOD | TSS | Fecal Coliform | |
| 48 | 0.80 MLD STP at Krishnapur, Distt- Nainital. (Operated by: Uttarakhand Jal Sansthan) | 6.51 | 255 | 307 | 7.33 | 28 | 36 | 280 | |
| 49 | 1.25 MLD STP at Bheemtal, Distt- Nainital. (Operated by: Uttarakhand Jal Sansthan) | 6.20 | 240 | 291 | 7.38 | 24 | 30 | 240 | |
| 50 | 1.25 MLD STP at Nirada, Distt- Pithoragarh. (Operated by: Uttarakhand Peyjal Nigam) | 6.91 | 245 | 299 | 7.28 | 26 | 33 | 430 | |
| 51 | 5.0 MLD STP at Aincholi, Distt- Pithoragarh. (Operated by: Uttarakhand Peyjal Nigam) | 6.65 | 260 | 316 | 7.74 | 20 | 25 | 350 | |
| 52 | 1.5 MLD STP at Puchdi, Ramnagar, Nainital. (Operated by: Uttarakhand Jal Sansthan) | 7.13 | 180 | 222 | 7.30 | 6.0 | 08 | 94 | |
| 53 | 7.0 MLD STP Transport Nagar, Ramnagar, Distt-Nainital. (Operated by: Uttarakhand Jal Sansthan) | 7.10 | 220 | 274 | 7.82 | 9.0 | 10 | 84 | |
| 54 | 0.45 MLD STP Narayan Nagar , Distt- Nainital . (Operated by: Uttarakhand Jal Sansthan) | 6.22 | 280 | 346 | 7.18 | 20 | 24 | 220 | |
| Sewag | e Treatment final effluent standards (A | s Notifie | d by MoEl | F&CC) | 6.5-9.0 | 30 | <100 | <1000 | |

^{*12} STPs in the district of Chamoli (Gopeshwar-03, Chamoli-02, Nandprayag-02 & Karanprayag-05) were found closed/Non-operational during visit (Date of Visit / inspection: 23-07-2023), and monitoring of Gangotri STP (District-Uttarkashi) not performed because of heavy landslide near Gangnanion dated 28-07-2023.